
Approved For ease 2002/10/16 : CIA-RDP67B00511B000100140056-5



12 December 1960

Dear Milt:

ELG tells me you are having some trouble in unwinding our material in your device. I gather that there is an occasional tendency for successive convolutions to stick slightly, changing the angle by which the material leaves the spool.

We are looking into the problem, but could do a better job of analysis if you could send us a short piece of material with which you have noticed trouble. Weld like the trouble area marked, with at least one convolution on either side. Perhaps you can get such a sample the next time you run.

JSM:kl cc: LEW /

J. S. M.